BCTI30410



30" Induction Cooktop





9
4 Induction
7" x 7-7/8" - 2,100 W / 3,700 W
7" x 7-7/8" - 2,100 W / 3,700 W
-
9" – 2,600 W / 3,700 W
11" - 2,600 W / 3,700 W
Yes
Yes



PREMIUM TECHNOLOGY



INDUCTION COOKING Induction technology provides fast and precise results by directly heating pots and pans instead of the cooktop surface



POWER BOOST Add a boost or double boost of power so you can quickly heat a pan for searing or stir-frying, or boil water fast.



PRECISE TEMPERATURE CONTROL

9 cooking levels put you in control to boil water rapidly or delicately melt chocolate-plus everything in between.

BCTI30410





FEATURES & PERFORMANCE CONTINUED

Keep Warm Function	Yes
Pan Detection	Yes
Residual Heat Indicators	Yes
Independent Zone Timers	Yes

TECHNICAL INFORMATION

Total Power Consumption	7,400 W
Volts / Frequency	240/208 V, 60 Hz
Min. Circuit Breaker Size	40 A
Electrical Connection	Flexible Conduit, 3-Wire or 4-Wire

DIMENSIONS & WEIGHT Product (H x W x D) (in) 2 3/8 x 30 11/16 x 20 7/16 Required Cutout Size (W x D) (in) 29 1/2 W x 19 5/16 Carton (H x W x D) (in) 4 3/4 x 31 1/2 x 23 5/8 Product Weight (lbs) 22.04 Shipping Weight (lbs) 26.46

WARRANTY

Entire Appliance

2-Year Full Warranty

Top View



Side View



Front View





BCTI30410



30" Induction Cooktop

Clearances



Under Counter - Side View



Installation Above a Built-in Oven



NOTE TO THE INSTALLER: All height, width, and depth dimensions are shown in inches (as well as metric). Beko U.S., Inc. reserves the absolute and unrestricted right to change product materials and specifications, at any time, without notice. Please visit our website, www.BekoAppliances.com, or call 888.352.2356 to verify the latest specifications with final dimensional data and other details prior to installation and making a cutout. Applicable product limited warranty information may be found in accompanying product materials, or you may contact your account manager for further details. Proper installation is the responsibility of the installer. Product failure due to improper installation is not covered under the Limited Warranty.