


# HEKMAN®

X A HOWARD MILLER COMPANY

## 27978 LIFT DESK

HARDWARE LIST							
A	B	C	D	E	F	G	H
ALLEN BOLT M6 X 40 (12 PCS.)	ALLEN BOLT M6 X 60 (8 PCS.)	SPRING W. M6 20 PCS.	FLAT W. M6 20 PCS.	CORD CLAMP 2 PCS.	NYLON CORD CLAMP 1 PC.	SCREW Ø6 X $\frac{1}{2}$ " 1 PC.	ALLEN KEY L4 (FOR ALLEN BOLT) 1 PC.
							




## Assembly Instruction

### STEP 1.

LAY TOP ASSEMBLY OF THE TABLE DESK UPSIDE DOWN ON A SOFT, CLEAN AND FLAT SURFACE. PULL OUT DRAWERS ON SOFT MATERIAL TO PREVENT SCRATCHING SURFACES.

ALIGN METAL LEGS (2) TO THE HOLES IN THE TOP ASSEMBLY (1) AND CONNECT USING FLAT WASHER (D), SPRING WASHER (C), ALLEN BOLT (A) AND ALLEN KEY (E) PROVIDED.



### STEP 2.

PLUG THE CABLE WHICH ATTACHED ON THE LEG ONTO THE POWER SUPPLY WHICH LOCATED ON THE BOTTOM OF TOP PANEL.

