



ASSEMBLY INSTRUCTION

SDR-2916 / BROCK BS


(1)X1




(6)X1



(2)X1




(7)X+1 EXTRA



(3)X1




(8)X+1 EXTRA



M6*20MM


(4)X1




(9)X1




(5)X1




①




②



③



④



⑤

