

Assembly Instructions

ITEM NO. D4128-30

GWENDOLYN SERVER

Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts, which may have come loose inside the carton during shipment. Identify and count all items and compare with the PARTS LIST and/or HARDWARE LIST shown below.

1. We recommend that you assemble this product with the assistance of another person; this will make the assembly easier, and will help eliminate damage to the product or injury to persons during assembly.
2. Please do not tighten screws or bolts until the assembly is completed.
3. To level the chairs or table, before tightening all the screws, the chairs or table must be placed on a flat surface and then tighten the screws.
4. Please put all parts on a non-abrasive floor before assembly and follow the assembly steps to assemble your newly purchased product correctly and efficiently.

PARTS LIST



NO.	COMPONENT	SKETCH	QTY
A	SERVER		1PC

HARDWARE LIST

NO.	COMPONENT	SKETCH	QTY
1	Anti-Tipping Kit		1 PC

STEP 1

To level the Server (A), stand the server upright on a flat surface and adjust by twisting the levelers on the base.



Assembly Instructions

ITEM NO. D4128-30

GWENDOLYN SERVER

STEP 2

Follow the instructions from the Anti-Tipping Kit (1) to install the Anti-Tipping Restraint.

