Assembly Instruction for
BAR TABLE SINGLE PACK (TABLE + 3 STOOLS)
CDOL100BTSP/CDOL100BTSPE/D.14030.BTSP/CDOL300BTSP

Caution: Please read instructions thoroughly before unpacking assembly parts.Sharp,exposed staple tips can cause injury,therefore,for your protection,please remove any exposed staples used in packing.

1. We recommend that you should assemble this product with the assistance of another person;this will make assembly easier, and will help to eliminate damage to the product or injury to persons during assembly.
2. Be sure to check all packing materials carefully for small parts that may have come loose inside the carton during shipment.
3. Please do not over tighten screws or bolts.
4. Please Put all parts on a non-abrasive floor before assembly, and follow the assembly steps to assemble your newly purchased product correctly and efficiently.

PART LIST

No.	PART DESC	CODE.	Q'TY
A	STOOL SEAT FARME WITH CUSHION	PCDOL100BTSPSEA	3
B	STOOL LEGS	PCDOL100BTSPSLEG	12
C	STOOL FRONT &BACK STRETCHER	PCDOL100BTSPSTR1	6
D	STOOL LEFT&RIGHT STRETCHER	PCDOL100BTSPSTR2	6
E	COUNTER BAR TABLE TOP		1
F	COUNTER BAR L&R LEG	PCDOL100BTSPBLEG	4
G	COUNTER BAR CENTERLINE RAIL	PCDOL100BTSPBRAL1	1
H	COUNTER BAR L&R SIDE RAIL	PCDOL100BTSPBRAL2	2

HARDWARE LIST

| NO.		HARDWARE DESC	CODE.	Q'TY
1		ALLEN BOLT (1/4″x 50mm)		24
2		SPRING WASHER(1/4″)		24
3		FLAT WASHER (1/4″x 19mm)	PCDOL100BTSPHW2 (STOOL)	24
4		SCREW (50mm		24
5		ALLEN KEY(M4)		3
6		ALLEN BOLT (5/16″x 65mm)		8
7		SPRING WASHER (5/16″)		8
8		FLAT WASHER(5/16″x 22mm)	PCDOL100BTSPHW1 (TABLE)	8
9		ALLEN KEY (M5)		1
10		SCREW (50mm		6

NOTES ： Do not fully tighten any bolts until last step.

### TOOLS REQUIRED (NOT PROVIDED)

Phillips Screw Driver

STEP : 1

STEP : 2

STEP : 3

COMPLETED

MADE IN VIETNAM