







ASSEMBLY INSTRUCTION
INSTRUCCIONES

2761T-48 COUNTER HIGH TABLE
2761T-48 MESA ALTA DE MOSTRADOR


PARTS LIST

1		1PC/PIEZA
2		1PC/PIEZA
3		1PC/PIEZA
4		4PCS/PIEZAS


HARDWARE LIST

A	 Bolt Ø5/16"x 18x 2 3/8"	8PCS/PIEZAS
B	 Allen key 4x58mm	1PC/PIEZA
C	 Screws M4 x 1 5/8"	5PCS/PIEZAS
ASSEMBLY TOOL NOT INCLUDED 		


Step 1
Paso 1




Step 2
Paso 2



Step 3
Paso 3



Step 4
Paso 4



DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED
NO APRETER LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.