




Sunset Trading

ASSEMBLY INSTRUCTION

SKU: CR-G5124-4147

STEP1




STEP1-Attach the Center connector (4) to Leg (2) with Bolt (A) as pictured

STEP2




STEP2-Attach additional Leg (2) to the center connector (4) with Bolt (A) as pictured.

STEP3




STEP3- Attach remaining legs (2) to the leg assembly as pictured

STEP4



STEP4- Attach remaining legs (2) to the leg assembly as pictured


STEP5



STEP5- Attach the leg assembly to the bottom side of the glass with Bolts (D) as pictured and tighten all bolts.


Tighten all the bolts

STEP6



STEP6- Install the Top (3) and Bottom (5) covers with Bolt (C) and tighten

STEP7



A	4Pcs	M8*15mm
B	1Pc	6mm
C	1Pc	M8*40mm
D	4Pcs	M8*12mm
E	4Pcs	Φ8x22mm
F	4Pcs	Φ8x16mm


701 E Industrial Pk Dr
Manchester, NH 03109
sunsettrading.com

Please Contact us if you are
Missing Parts or have any Questions
877-364-8464
info@sunsettrading.com

Thank you for purchasing this quality product! It has been engineered for easy assembly yet constructed for durability. Please take the time to read and follow the instructions while assembling.

△ IMPORTANT NOTES:

- Keep all hardware and small parts out of reach of children.
 - Remove all staples and packing straps before you start to assemble.
 - Do not discard main car tons and wrapping material until assembly is complete.
 - Check to be sure you have all parts and hardware. Place all product parts on a clean, soft surface to avoid parts from being scratched.
 - Do not tighten all screws /bolts until completely assembled.
 - Do not attempt to repair or modify parts that are broken or defective. Please contact us with Item NO and Quantity immediately.
- Enjoy your new Furniture!



		Part Description	Quantity
G5051-41 G5051-44 G5124-41	1	Top glass	1
	2	Leg	4
	3	Top Cover	1
G5051-47 G5051-50 G5124-47	4	Center block	1
	5	Bottom cover	1
	6	 M8x12-Φ32x35mm	4