


# ASSEMBLY INSTRUCTION

Model : D2279DT


Description : DINING TABLE

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.


Step 1:



Step 2:



Step 3:




## PART LIST :

| No. | Description | Diagram | Quantity |
|-----|-------------|---------|----------|
| A   | table top   |         | 1        |
| B   | Column      |         | 1        |
| C   | wood plate  |         | 1        |
| D   | table base  |         | 1        |






## HARDWARE LIST :

| No. | Description | Diagram | Size       | Quantity |
|-----|-------------|---------|------------|----------|
| E   | Stud        |         | M8 x 615mm | 4        |
| F   | Flat washer |         | Ø20 x10mm  | 4        |
| G   | nut         |         | M8 x 25mm  | 4        |
| H   | Bolt        |         | M8 x 35mm  | 4        |
| I   | Allen key   |         | M5         | 1        |

Finished



Made In China




# ASSEMBLY INSTRUCTION

Model : D4878DC

Description: DINING CHAIR

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

## STEP 1



### PART LIST:

| NO. | Description | Diagram | Quantity |
|-----|-------------|---------|----------|
| A   | Legs        |         | 1        |
| B   | Backrest    |         | 1        |

### HARDWARE LIST:

|   |                       |  |   |
|---|-----------------------|--|---|
| C | Bolt M6X16mm          |  | 2 |
| D | Bolt M6X30mm          |  | 2 |
| E | flat washer $\phi$ 16 |  | 4 |
| F | Allen Key M4          |  | 1 |

### PRE-FIX HARDWARE LIST:

|   |                 |  |   |
|---|-----------------|--|---|
| G | Mechanism plate |  | 1 |
| H | Plastic feet    |  | 4 |

Assembly backrest(B) to the legs(A) with bolt(C) and bolt(D) by using flat washer(E) and allen key(F)

## STEP 2



Finished

Made In China