




CP1110C2-HA



CP1110C2-HA



A x2
Spec: $\phi 15 * \phi 8 * L44$




B x2
Spec:




C x2
Spec:



D x2
Spec:



E x1
Spec: 5#




F x2
Spec:



G x1
Spec: 10g



H x4
Spec: $\phi 8 * 30$




I x5
Spec: $\phi 7 * L30$



J x5
Spec: $\phi 15 * H12$




K x4
Spec: $\phi 8 * \phi 18$



L x4
Spec: M6*30




M x5
Spec:



1

2



3

