
ASSEMBLY INSTRUCTION MODEL: #30500F-HB/3C501F-FB/30502F-R/30508 FULL BED

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Separate, identify anh count all parts and metal hardware. Compare with parts list to be sure all parts are present. If any part(s) are missing or damaged, please contact your local furniture dealer. For efficient and speedy service, please indicate the model number and code letter of part(s) needed.

***	Do not fully	tighten	screws	until fully	assembled ***
-----	--------------	---------	--------	-------------	---------------

PARTS LIST				HARDWARE LIST			
NO	DESCRIPTION	SKETCH	QTY	NO	DESCRIPTION	SKETCH	QTY
Α	HEADBOARD	A	1 Pc	1	BOLT		8 Pcs
В	FOOTBOARD		1 Pc	2	FLAT WASHER	8	8 Pcs
С	SIDE RAILS		2 Pcs	3	NUT	6	8 Pcs
D	SLATS	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TO THE PERSON NAMED IN COLUMN T	1 set	4	SPANNER WRENCH	Js	1 Pc
Е	TRUNDLE		1 Pc	5-	SCREW	^®	26 Pcs



ASSEMBLY INSTRUCTION MODEL: #30500F-HB FULL BED HEADBOARD

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Separate, identify anh count all parts and metal hardware. Compare with parts list to be sure all parts are present. If any part(s) are missing or damaged, please contact your local furniture dealer. For efficient and speedy service, please indicate the model number and code letter of part(s) needed.

*** Do not fully tighten screws until fully assembled ***

	PARTS LIST				HARDWARE LIST			
NO	DESCRIPTION	SKETCH	QTY	NO	DESCRIPTION	SKETCH	QTY	
A	HEADBOARD :	A	1 Pc	1	BOLT	(One money to	6 Pcs	
В	LEGS	1	2 Pcs	2	FLAT WASHER	0	6 Pcs	
-	:	. Ψ		3	ALLEN WRENCH	L	1 Pc	

