
ASSEMBLY INSTRUCTION

Model:D4126DT


Description: DINING TABLE

Thank you for purchasing this quality product space. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.










Remove the upper and lower shipping block from the pedestal

Step 4 Assembly the metal glass collector bracket to thepedestal




Step 3 Attach the bottom plate to the pedestal

PART LIST:						
NO.	Description	Diagram	Quantity			
А	Table glass top	•••	1			
В	Table column		1			
С	Table base	<u></u>	1			


HARDWARE LIST:							
NO.	Description		Diagram	Quantity			
D	Flat washer	ф20×T2.0mm	0	6			
Е	Bolt	M8×45mm	0	6			
F	Bolt	M8×20mm	0	2			
G	Bolt/Nut/ Flat washer	M8×65mm/M8/ ф20×T2.0mm		2			
Н	Metal	136×36×10mm		1			
I	Allen key	3#		1			
J	Allen key	5#		1			

14#



Finished

Socket wrench



Made In China

1


ASSEMBLY INSTRUCTION

Model: D4126DC/D4127DC

Description : Dining chair


Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment


Step 1:



PART LIST :								
No.	Descript	ion		Diagram	Quanti			
A	Legs			C	1			
В	Seat			1				
С	Backrest				1			
HAI	RDWARE L	.IST	:					
No.	Description	Diagram		Size	Quantit			
D	Bolt			M8*20	3			
Е	Bolt	9)11111		M6*16	4			
F	Flat washer	0		Ø6 * Ø16	4			
G	Allen key			M6	1			
	Allen key			M4	1			

Step 2:





Poor Assembly Picture: Step 2-a:Put the backrest(C) into the holes on the seat(B), press a little to make the screw holes on the backrest(C) are align with the screw holes on the seat(B), lock these four holes with bolts(E). (Note: do not lock completely at this step) Step 2-b:Press the backrest(C) harder to make the Finished: inner surface of the back close contact with the seat(B) and then 100% lock the four bolts(E). (Note: do not lock the screws when the back and cushion are at untight contact position like poor assembly picutre)