
ASSEMBLY INSTRUCTION

Description: BAR TABLE Model: M208BT

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

Step 1:



PART LIST:

NO.	Description	Diagram	Quantity
А	Тор	(:)	1pcs
В	Rod	(1937-1918 MILES II)	3pcs
С	Leg		1pcs
D	Decotative washer	0	3pcs
Е	Base	000	1pcs


HARDWARE LIST:

NO.	Description	Diagram	Size	Quantity
F	Flat washer	0	Ф10х25тт	3pcs
G	Nut	@	M10	3pcs
Н	Socket key	#	M10	1pcs


PREFIX HARDWARE LIST:

I	Caps	0	6pcs
---	------	---	------


Step 2:



Step 3:



Step 4: Finsihed



Made In China