


ASSEMBLY INSTRUCTIONS

X A HOWARD MILLER COMPANY

7-9321 CREDENZA 7-9322 DECK

NO.	Hardware List		Q'ty
A		screw (M4 * 20)	4
	Note: Tools required screw driver		



PLACE THE TOP ON THE BASE TOP, SECURE THE UNIT BY USING THE SUPPLIED MENDING PLATE AND SCREWS ON THE BACK.