

Assembly Instructions

B532-110: CONSTANTINE 6/6-6/0 EK/WK HEADBOARD

B532-120: CONSTANTINE 6/6-6/0 EK/WK FOOTBOARD & SLATS B532-330: CONSTANTINE 5/0-6/6 Q/EK PANEL SIDE RAILS

Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts, which may have come loose inside the carton during shipment. Identify and count all items and compare with the PARTS LIST and/or HARDWARE LIST shown below.

CAUTION: Please read the instructions thoroughly before assembly.


- 1.We recommend that you assemble this product with the assistance of another person; this will make the assembly easier, and will help eliminate damage to the product or injury to persons during assembly.
- 2. Please do not over tighten screws or bolts until the assembly is completed.
- 3.Please put all parts on a non-abrasive floor before assembly, and follow the assembly steps to assemble your newly purchased product correctly and efficiently.

PARTS LIST

		I	
NO:	COMPONENT	DRAWING	Q'TY
А	HEADBOARD		1PC
В	FOOTBOARD		1PC
С	SIDE RAIL		2PCS
D	LEFT LEG HEADBOARD		1PC
Е	RIGHT LEG HEADBOARD		1PC
F	HEADBOARD SLAT		1PC
G	SLATS		4PCS
Н	SUPPORT LEGS	₹	8PCS

HARDWARE LIST

NO:	COMPONENT	DRAWING	Q'TY
1	Bolt Φ5/16"x2"L		10PCS
2	Lock washer Ø5/16"	0	10PCS
3	Flat washer Ø5/16"	0	10PCS
4	Allen Key 1/6"		1PC
5	Threaded Bolt Ø5/16"x3-1/2"L	G0000000000000000000000000000000000000	8PCS
6	Flat washer	<u> </u>	8PCS
7	Hex Nut Ø5/16"	©	8PCS
8	Ø5/16" Wrench 1/2"		1PC
9	Wood screw Ø8x1-1/4"L	(Annum-	8PCS





PAGE: 10F3





Assembly Instructions B532-110: CONSTANTINE 6/6-6/0 EK/WK HEADBOARD

B532-110: CONSTANTINE 6/6-6/0 EK/WK HEADBOARD B532-120: CONSTANTINE 6/6-6/0 EK/WK FOOTBOARD & SLATS B532-330: CONSTANTINE 5/0-6/6 Q/EK PANEL SIDE RAILS










PAGE: 2OF3



Assembly Instructions B532-110: CONSTANTINE 6/6-6/0 EK/WK HEADBOARD

B532-120: CONSTANTINE 6/6-6/0 EK/WK FOOTBOARD & SLATS B532-330: CONSTANTINE 5/0-6/6 Q/EK PANEL SIDE RAILS

STEP 5



COMPLETE

