
ASSEMBLY INSTRUCTION

Model: D915BS Description: Bar Stool

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

Step 1:



Firstly, fix the backrest with the chair leg but do not fully tighten the bolt(D).

PART LIST:


NO.	Description	Diagram	Quantity
A	Chair leg		1
В	Chair backrest		1
С	Chair seat		1

HARDWARE LIST:

- [
	NO.	Description	Diagram	Size	Quantity	
	D	Bolt		$M6 \times 13$ mm	4	
	Е	Bolt		$M6 \times 20$ mm	2	
	F	Bolt		$M6 \times 25 \mathrm{mm}$	2	
	G	Flat washer	0	ø 16× ø 6mm	4	
	Н	Allen key		4#	1	

Step 2:





Assemble the chair seat with the chair leg but do not fully tighten the bolt(E&F).



Finally, lean the chair with extra care and tighten the bolt. (D&E&F).


Made In China

ASSEMBLY INSTRUCTION

Description: BAR TABLE Model: M208BT

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

Step 1:



PART LIST:

NO.	Description	Diagram	Quantity
А	Тор	$\boxed{ \ \vdots \ }$	1pcs
В	Rod	(1022UK MILLER)	3pcs
С	Leg		1pcs
D	Decotative washer	©	3pcs
Е	Base	•••	1pcs


HARDWARE LIST:


NO.	Description	Diagram	Size	Quantity
F	Flat washer	0	Ф10х25тт	3pcs
G	Nut	@	M10	3pcs
Н	Socket key	#	M10	1pcs

PREFIX HARDWARE LIST:

I	Caps	0	6pcs
---	------	---	------

Step 2:





Step 4: Finsihed

