

Cleaning & Care

- Allow all components to cool completely before cleaning
- Wipe down motor with a damp cloth only (do not submerge)
- Wash the spit rod and forks in warm, soapy water
- Use a brush or steel wool for stuck-on bits
- Dry thoroughly before storage