
ITEM# 11400

Empiria Mixed Metal and Wood Laptop Computer Desk



Hardware List

Item	Illustration	Description	Quantity
1		Bolt 1/4" x 1-3/4"	8 PCS
2		Lock Washer	8 PCS
3		Washer 1/4" x 5/8"	8 PCS
4		Allen Wrench	1 PC
5		Anti- tipping Hardware	1 PC

____1___

----2----


Parts List

Item	Illustration	Description	Quantity
A		Top Assembly	1PC
В		Side Frame	2PCS

Assembly Instructions Two person assembly recommended.


Step 1

Place top assembly upside down on a soft surface. Fasten the Side Frames with (8) bolts, flat washers and lock washers using the Allen wrench. Do not tighten yet.




Step 2

Ensure they are properly aligned and tighten all bolts.



Step 3


Adjust levelers on bottom of legs.



Step 4

Fasten the anti-tipping hardware with 2 screws on the back of desk and the other 2 screws onto the wall.

Note: This step only applies after running all the computer cables through the wire management hole and the black cover disc is already in place.



Wire management hole on back of desk: pull the disk out, run wires, and snap disk back in place.

