

## **ASSEMBLY INSTRUCTION**

ITEM: 628-85689-89 Contours Console


Thank you for purchasing this quality product. Be sure to unpack carefully looking for small parts which may have come loose during shipment.

Read all instruction and study the drawing carefully before starting the assembly process.

HARDWARE PACK					
NO.	DRAWING	DESCRIPTION SIZE		Q'TY	
А	Allen Wrench		108*76*5MM	1 PC	
В	•	Bolt	5/16*55mm	2 PCS	
С		Bolt	5/16*30mm	8 PCS	
D		Lock Washer	5/6"	10 PCS	
Е	0	Flat Washer	5/16*22mm	10 PCS	

PARTS LIST					
NO.	DRAWING	DESCRIPTION	Q'TY		
1		Stretcher	1 PC		
2		Leg Base	2 PCS		
3		Table Top	1 PC		

STEP 1



Step 1: Attach stretcher (1) to leg bases (2) by using bolts (B), lock washers (D), flat washers (E) and allen wrench (A).

Step 2: Attach leg bases (2) to the table top (3) by using bolts (C), lock washers (D), flat washers (E) and allen wrench (A).



## **ASSEMBLY INSTRUCTION**

ITEM: 628-85689-89 Contours Console

Thank you for purchasing this quality product. Be sure to unpack carefully looking for small parts which may have come loose during shipment.

Read all instruction and study the drawing carefully before starting the assembly process.

