

ASSEMBLY INSTRUCTIONS


MODEL : 19564CK
C.KING BED(5 +5)

(BOX 1)


BOX OF HEADBOARD

NO	ITEM	QTY
A	HEADBOARD	1 PC
B	FOOTBOARD	1 PC
C	HB LEG L&R	2 PCS
D	BED SLAT	5 PCS
E	BED SLAT SUPPORT	5 PCS

STEP 1 : Attach Head Board Leg (C) to Head Board (A) as shown using JCBC BOLT(1)with Spring Washer (2), Flat washer (3) and securing with ALLEN WRENCH (4)



STEP 2 : Hook SIDE RAIL (F) TO HEAD BOARD (A) closely and push down to fit. repeat step 2 with other end of rail to hook onto FOOTBOARD (B).



(BOX 2)

BOX OF SIDE RAIL

NO	ITEM	QTY
F	SIDE RAIL	2 PCS

Step 3: Fix the Bed Slat Support (E), with adjuster to Bed Slat (D).Lastly, tighten the Bed Slat (D) with L Bracket (6) and tighten with Flat Head Screw (5) as shown loosen and tighten the adjuster for stability of bed.

(NOTE: THE SETUP MUST DONE AT THE DECIDED LOCATION FOR THE BED TO OBTAIN PERFECT STABILITY)




HARDWARE LIST

NO	ITEM	QTY
1	JCBC BOLT M6 x 30MM BLK	6 PCS
2	SPRING WASHER 1/4" RBW	6 PCS
3	FLAT WASHER 1/4" ID x 13mm QD BLK	6 PCS
4	ALLEN KEY m4 x 65mm BLK	1 PC

(BOX 2)

HARDWARE LIST

NO	ITEM	QTY
5	PAN HEAD CHIPBOARD SCREW m3.5 x 16mm RBW	20 PCS
6	L-BRACKET	10 PCS



NOTE : MUST TIGHTEN SCREWS PERIODCALLY WITH USE SCREW WILL BECOME LOOSE CHECK TIGHTNESS OF ALL SCREW EVERY 6-8 WEEKS.