


ASSEMBLY INSTRUCTIONS 2767SET COUNTER HIGH TABLE


INSTRUCCIONES 2767SET MESA ALTA DE MOSTRADOR

PARTS LIST


HARDWARE LIST

NO.	DESCRIPTION	SKETCH	Q'TY	NO.	DRAWING	DESCRIPTION	Q'TY
1	TABLE TOP		1	A		Ø5/16"-18x2-3/8"L	8
2	TABLE LEG		4	B		M4 SMALL ALLEN KEY	1

STEP/PASO 1:



STEP/PASO 2:



DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.
NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.

ASSEMBLY INSTRUCTIONS 2767SET COUNTER HIGH CHAIR

INSTRUCCIONES 2767SET SILLA ALTA DE MOSTRADOR


PARTS LIST

NO.	DESCRIPTION	SKETCH	Q'TY
1	CHAIR BACK		1
2	SEAT BOARD		1
3	FRONT LEG (L&R)		2
4	SIDE STRETCHER (L&R)		2
5	FRONT STRETCHER		1


HARDWARE LIST

NO.	DRAWING	DESCRIPTION	Q'TY
A		Ø1/4"-20x2-3/8"L (Front leg)	4
B		Ø1/4"-20x3"L (Chair back leg corner)	4
C		Ø1/4"-20x1-1/2"L (Chair back center)	2
D		M4 SMALL ALLEN KEY	1
E		SCREW #4x45mm	6
F		WOODEN DOWEL Ø10x30mm	1


ASSEMBLY TOOL
NOT INCLUDED





STEP/PASO 1:



STEP/PASO 2:



STEP/PASO 3:



PAGE 1 OF 1

DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.
NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.