



ASSEMBLY INSTRUCTIONS

COASTER FINE FURNITURE



Fine Furniture for every stage of life

710217
END TABLE

ITEM: 710217 (B1-B2)



ASSEMBLY INSTRUCTIONS

ASSEMBLY TIPS:

1. Remove hardware from box and sort by size.
2. Please check to see that all hardware and parts are present prior to start of assembly.
3. Please follow attached instructions in the same sequence as numbered to assure fast & easy assembly.



WARNING!

1. Don't attempt to repair or modify parts that are broken or defective. Please contact the store immediately.
2. This product is for home use only and not intended for commercial establishments.



ASSEMBLY TIME

10 MINUTES

PARTS IDENTIFICATION

B1 (BOX 1)


A TOP MARBLE



1PC

B2 (BOX 2)

B LONG LEG



4PCS

C LEG SUPPORT



1PC

NOTE:

Phillips head screw driver is required in the assembly process; however, manufacturer does not provide this item.

ITEM:710217 (B1-B2)



ASSEMBLY INSTRUCTIONS

ASSEMBLY TIPS:

1. Remove hardware from box and sort by size.
2. Please check to see that all hardware and parts are present prior to start of assembly.
3. Please follow attached instructions in the same sequence as numbered to assure fast & easy assembly.



WARNING!

1. Don't attempt to repair or modify parts that are broken or defective. Please contact the store immediately.
2. This product is for home use only and not intended for commercial establishments.

HARDWARE IDENTIFICATION

Z-HARDWARE PACK IS LOCATED IN 710217 (B2)

1	ALLEN WRENCH		1PC
2	SHORT BOLT (M8*16mm)		8PCS
3	FLAT WASHER		8PCS

Hardware pack is located in 710217 B2

NOTE:


Phillips head screw driver is required in the assembly process; however, manufacturer does not provide this item.

ITEM:710217 (B1-B2)


ASSEMBLY INSTRUCTIONS

STEP 1


DON'T TIGHT THE LEGS ALL THE WAY DONE,UNTIL ALL THE LEGS ARE CONNECTED




STEP 2




STEP 3



STEP 4





STEP 5



TIGHT THE BASE AND TOP TOGETHER

STEP 6






Note : Dimension tolerance $\pm 5\%$



ASSEMBLY INSTRUCTIONS COASTER FINE FURNITURE



Fine Furniture for every stage of life

710218
COFFEE TABLE

ITEM: 710218 (B1-B2)



ASSEMBLY INSTRUCTIONS

ASSEMBLY TIPS:

1. Remove hardware from box and sort by size.
2. Please check to see that all hardware and parts are present prior to start of assembly.
3. Please follow attached instructions in the same sequence as numbered to assure fast & easy assembly.



WARNING!

1. Don't attempt to repair or modify parts that are broken or defective. Please contact the store immediately.
2. This product is for home use only and not intended for commercial establishments.




ASSEMBLY TIME

15 MINUTES

PARTS IDENTIFICATION

B1 (BOX 1)


A TOP MARBLE



1PC

B2 (BOX 2)

B LONG LEG



2PCS

C SMALL LEG



2PCS

D LEG SUPPORT



1PC

NOTE:

Phillips head screw driver is required in the assembly process; however, manufacturer does not provide this item.

ITEM:710218 (B1-B2)



ASSEMBLY INSTRUCTIONS

ASSEMBLY TIPS:

1. Remove hardware from box and sort by size.
2. Please check to see that all hardware and parts are present prior to start of assembly.
3. Please follow attached instructions in the same sequence as numbered to assure fast & easy assembly.



WARNING!

1. Don't attempt to repair or modify parts that are broken or defective. Please contact the store immediately.
2. This product is for home use only and not intended for commercial establishments.

HARDWARE IDENTIFICATION

Z- HARDWARE PACK IS LOCATED IN 710218 (B2)

1 ALLEN WRENCH



1PC

2 SHORT BOLT
(M8*16mm)



12PCS

3 FLAT WASHER



12PCS

Hardware pack is located in 710218 B2


NOTE:

Phillips head screw driver is required in the assembly process; however, manufacturer does not provide this item.


ITEM:710218 (B1-B2)

ASSEMBLY INSTRUCTIONS


STEP 1




STEP 2




STEP 3



STEP 4





STEP 5



TIGHT THE BASE AND TOP TOGETHER

STEP 6





Note : Dimension tolerance $\pm 5\%$