


ASSEMBLY INSTRUCTIONS

INSTRUCCIONES

2716T-4060/2717T-4060 COUNTER HIGH TABLE

2716T-4060/2717T-4060 MESA ALTA DE MOSTRADOR


(BOX 1) TABLE TOP

1		1PC / PIEZA
----------	---	-------------

(BOX 2) TABLE BASE

2		1PC / PIEZA
3		4PCS / PIEZAS
4		1PC / PIEZA
5		2PCS / PIEZAS


(BOX 1) HARDWARE LIST

A		BOLT Ø5/16" x 18 x 2"	12PCS / PIEZAS
B		SCREW #8x1-1/2"	8PCS / PIEZAS
C		ALLEN WRENCH 4mm	1PC / PIEZA


ASSEMBLY INSTRUCTIONS

INSTRUCCIONES


STEP 1




STEP 2



STEP 3



STEP 4



DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.
NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.