



Parts

- 1. 2 Wall Brackets
- 2. Latex Gloves
- 3. Screen Cleaner

1

2







External Lens Only - 2.35:1 Projector Throw Distance

To eliminate PIN CUSHION and BARREL DISTORTION with Zero Edge you must follow the information below.


Zero Edge <u>Diagonal Size</u>	Minimum (Throw Distance)	Maximum (Throw Distance)
150"	(22' - 1")	(23' - 0")
133"	(20' - 5")	(21' - 3")
120"	(18' - 5")	(19' - 2")
110"	(16-10")	(17' - 7")

Important Note: The projector used must have a minimum zoom capability of 2.7 Projectors with 2.35:1 lens memory modes will have no issues with Zero!


Pure ZERO EDGE - Installation Instructions

Wall Mount

- 1. Measure for screen location. Attach brackets to wall using supplied fasteners based on measurements in diagram below. Ensure you hit studs or insert appropriately sized reinforcing hardware.
- 2. Lift screen onto brackets and slide to center on wall.
- 3. Remove the pre-mask layer from the screen surface.
- 4. Enjoy the show.




LED Lighting IR Hex Codes



Flying Mount

- 1. Note: Ceiling mounts must be installed such that each will hold at least 100 lbs.
- 2. Install ceiling mounts at approximately 1/2 screen width apart centered above the viewing area.
- 3. Slip the cable into the Flying Mount and pull through the slot on the back until the screen hangs at desired height. If you pull too far the screen can be lowered by pushing down the button on the top of the flying mount which allows the cable to be pulled back up through the bracket.
- 4. We recommend you don't cut the extra cables for future adjustability. Simply tape the extra cable to the back of the screen.



Help Line (512) 832-6939

www.screeninnovations.com