


ASSEMBLY INSTRUCTIONS

SKU: G5466-01/5466-03/5466-05/5466-07/5466-12


Chair

STEP1



Note: Please do not tighten all bolts or discard cartons and packaging material until assembly is completed, thank you!

STEP2



1		$\phi 8 \times 16$	8
2		M8*13mm	4
3		6mm	1
4		M8*30mm	2
5		M8*20mm	2
6		$\phi 8 \times 11.5$	4



Sunset Trading®


Please Contact us if you are Missing Parts or have any Questions

877-364-8464

info@sunsettrading.com



Please Contact us if you are Missing
 Parts or have any Questions
 877-364-8464
info@sunsettrading.com



	Part Description	Quantity
G5466	 Chair Back	1
	 Seat Cushion	1
	 Frame	1
	 Glide (Ø15*13)	4
	HDWR Hardware pack	1