



# ASSEMBLY INSTRUCTION

Step 1:



Finish :



## Hardware List:

| No.: | Description  | Drawing                                                                               | Size           | Q'ty |
|------|--------------|---------------------------------------------------------------------------------------|----------------|------|
| A    | Middle Bol.  |  | Ø5/16" X2-1/4" | 4    |
| B    | Lock Washer  |  | Ø5/16" X12mm   | 8    |
| C    | Flat Washer  |  | Ø5/16" X22mm   | 8    |
| D    | Long Bolt    |  | Ø5/16" X3-1/2" | 4    |
| E    | Short Bolt   |  | Ø5/16" X1-1/2" | 1    |
| F    | Allen Wrench |  | 5mm            | 1    |
| G    | Wood Screw   |  | #8"1-1/2"      | 6    |