

## PARTS AND HARDWARE.

## STEP 1.

## PARTS LIST

NO.	DESCRIPTION	IMAGE	Q'TY
P1	CABINET		1
HARDWARE LIST			
NO.	DESCRIPTION	IMAGE	Q′TY
Н1	METAL BRACKET	Ø	4
H2	NYLON STRAP	$\mathcal{O}$	2
Н3	long screwsø4x50		2
H4	SHORT SCREWS Ø4×20	~	2
H5	WALL PLUG M4		2
Н6	SCREW DRIVER		NOT PROVIDE



## NOTES.

Thank you for purchasing this quality product! Be sure to check all packing material carefully for small part that may have come loose inside the carton during shipping.

**CAUTION:** The item is heavy, assembly should be performed by two people.