

UTTERMOST

ASSEMBLY INSTRUCTION FOR ITEM # 50374

Parts:

- (A) Table top (1)
- (B) Base Leg (4)
- (C) Hexagonal Bolt M10 x 150 (8)
- (D) Spring Washer M10 (8)
- (E) Washer M10 x Ø30 (8)
- (F) Wrench M10 (1)

(A)



(B)



(C)



(D)




(E)




(F)



- ① To protect the finish of the table, place a blanket on the floor and rest the components on it before assembly.
- ② Position top (A) upside down as shown. 2 - 4 person task. And place legs in the correct positions according to each code.



- ③ Insert the bolts into the spring washer (D) and washer (E), then into their respective holes and tighten all bolts with the Wrench M10 (G) about 80%.



- ④ After the assembly is complete, carefully turn the table over (2 - 4 person task). Then, tighten all bolts to 100%. The table is ready to use!

