



ASSEMBLY INSTRUCTION

Step 1:



Finish :



Hardware List:

| No.: | Description  | Drawing | Size            | Q' |
|------|--------------|---------|-----------------|----|
| A    | Middle Bolt  |         | Ø5/16" X2 "     | 2  |
| B    | Lock Washer  |         | Ø5/16" X12mm    | 1  |
| C    | Flat Washer  |         | Ø5/16" X22mm    | 1  |
| D    | Long Bolt    |         | Ø5/16" X3-1/2 " | 2  |
| E    | Short Bolt   |         | Ø5/16" X1-3/4 " | 3  |
| F    | Wood Screw   |         | Ø8X1-3/4 "      | 2  |
| G    | Allen Wrench |         | 5mm             | 1  |